



SIERRA WIRELESS PRODUCT CHANGE NOTICE

OVERVIEW

DATE ISSUED:	July 24, 2018	TRACKING NUMBER:	4134642
ISSUED BY:	AirPrime Product Management		
PRODUCTS AFFECTED:	MC7455		
SKUS AFFECTED:	1103789		
BULLETIN:	Additional carriers support		
URGENCY:	Normal		
FOR DISTRIBUTION TO:	Customer using SKU affected		

Summary

Telus, Rogers, Bell, Vodafone, and US Cellular FW & PRI packages are being added to SKU 1103789.

SKU label will be updated from Rev A to Rev B

Old SKU Configuration (Rev A):

Carrier	FW Version
Generic	02.24.05.06
AT&T	02.24.05.06
Verizon	02.24.05.06
Sprint	02.24.03.00

New SKU Configuration (Rev B):

Carrier	FW Version
Generic	02.24.05.06
AT&T	02.24.05.06
Verizon	02.24.05.06
Sprint	02.24.03.00
Telus	02.24.05.06
Rogers	02.24.05.06
Bell	02.24.05.06
US Cellular	02.24.05.06
Vodafone	02.24.03.00

Timeline

The SKU update will be implemented and shippable by Aug 17, 2018.

More information

For more information please contact your Sierra Wireless sales/technical support person.